Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	600/300-301.ccls. and ((printer with command) same ((valid invalid) with (measurement result signal value)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 07:46
L2	0	"600"/\$.ccls. and ((printer with command) same ((valid invalid) with (measurement result signal value)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 07:46
L3	0	"600"/\$.ccls. and ((print\$3 with command) same ((valid invalid) with (measurement result signal value)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 07:46
L4	16	"600"/\$.ccls. and (print\$3 same ((valid invalid) with (measurement result signal value)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 07:47
L11	20	"600"/300-301.ccls. and ((determin\$ with (error noise noisy abnormal)) with (print\$3 output\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 08:16
L12	29	"600"/\$.ccls. and ((invalid\$ valid\$) with measurement with (print\$3 output\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 08:23
L13	17	"600"/\$.ccls. and (((invalid\$ valid\$) with measurement) same (print\$3 output\$3)) and printer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 08:21
L14	3	"128"/\$.ccls. and (((invalid\$ valid\$) with measurement) same (print\$3 output\$3)) and printer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 08:22

L15	1	"600"/\$.ccls. and (((determin\$5 judg\$5) with (normal abnormal) with measurement) same printer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 08:24
L16	4	"600"/\$.ccls. and (((determin\$5 judg\$5) with (normal abnormal) with (signal value parameter)) same printer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 08:25
L17	3	"600"/\$.ccls. and (((determin\$5 judg\$5) with (valid invalid) with (signal value parameter)) same printer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 08:26
L18	4	"600"/\$.ccls. and (((determin\$5 judg\$5) with (error) with (measurement signal value parameter)) same printer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 08:26
S1	18	"600"/\$.ccls. and colin and ((printer output) with normal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 15:32
S2	1	10/825374	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 07:31
S3	105	"600"/\$.ccls. and ((determin\$ with (error noise noisy abnormal)) same ((print printer display\$3 output\$3) with results))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 15:44
S4	59	"600"/\$.ccls. and ((determin\$ with (error noise noisy abnormal)) same ((print printer output\$3) with results))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 15:49

S5	178	"600"/\$.ccls. and ((print\$3 output\$3) with abnormal with (value measurement signal))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 15:45
S6	0	("2004/0260184").URPN.	USPAT	OR	OFF	2005/08/21 15:46
S7	35	"600"/\$.ccls. and ((determin\$ with (error noise noisy abnormal)) same ((abort\$ cancel\$) with (print\$3 output\$3)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/22 08:15
S8	129	"600"/\$.ccls. and ((print\$3 output\$3) with normal with abnormal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 15:52
S9	7	"600"/\$.ccls. and ((detect\$3 with failure) same print\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 15:53
S10	3	"600"/\$.ccls. and ((detect\$3 with failure) same (cancel\$ abort\$ discard\$)) and (print\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 15:54
S11	62	"600"/\$.ccls. and (discard\$3 same print\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 15:55
S12	12	("3672353" "3824990" "3874370" "3940692" "4023564" "4090505" "Re29921").PN. OR ("4339800").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/08/21 16:03
S14	11	"600"/\$.ccls. and ((data with invalid\$3) same (output\$3 print\$3)) and printer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 16:16

S15	44	"600"/\$.ccls. and (sensor with failure) and printer	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 16:41
S16	0	"600"/\$.ccls. and (printer same (("does not") with (print\$3 output\$3) with (abnormal invalid normal failure)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 16:46
S17	0	600/300,301.ccls. and (printer with (abnormal failure invalid) with (signal measurement results))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 16:48
S18	1	600/300,301.ccls. and (printer same ((abnormal failure invalid) with (signal measurement results)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 16:49
S19	29	"600"/\$.ccls. and (printer same ((abnormal failure invalid) with (signal measurement results)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 16:50
S20	3	"600"/300-301.ccls. and ((cancel\$ abort\$) with print\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 16:51
S21	0	"600"/300-301.ccls. and ((abnormal invalid noisy) with (signal measurement results) with (print\$3 output\$3) with message) and (normal with (print\$3 output\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2005/08/21 16:53
S22	1	"600"/300-301.ccls. and ((abnormal invalid noisy) with (print\$3 output\$3) with message) and (normal with (print\$3 output\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 16:53

S23		"600"/300-301.ccls. and (validat\$ same printer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 17:05
S24	6	600/485-507.ccls. and colin.asn. and printer and (normal with abnormal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 17:13
S25	1	600/485-507.ccls. and colin.asn. and (printer with normal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/21 17:46